

Unit #922
2019 Cross Country Pup
SN: 2C9PBK3L0KM183801

DATE	INVOICE #	NAME	AMOUNT	DEEP BASIN SHOP
Jul-22		Deep Basin Shop		
12-Jul-22	204092kms	Complete inspection. Grease trailer. Maintenance checklist completed.	Phil	1.00
28-Jul-22	211556kms	Complete inspection. Grease trailer. Tie up loose wires and hoses. Maintenance checklist completed.	Phil	1.50
Aug-22		Deep Basin Shop		
11-Aug-22	214839kms	Repaired wiring for tail gate. Replaced suspension air guage.	Phil	1.00
23-Aug-22	220529km	greased trailer no inspection	Phil	0.50
Sep-22		Deep Basin Shop		
2-Sep-22	223922km	serviced trailer, repared door hinge on air control box, complete insection	Phil	1.50
Nov-22		Deep Basin Shop		
22-Nov-22		Greased trailer. Tied up loose wiring and air lines. Replaced RH tarp cable.	Phil	2.50
Dec-22		Deep Basin Shop		
12-Dec-22	233215kms	CVIP inspection and repairs. Replaced air suspension gauge.	Phil	2.00
		Cassity Equipment		
12-Dec-22	19807	Perform CVIP "C" limited inspection	364.75	

Unit #922
2019 Cross Country Pup
SN: 2C9PBK3L0KM183801

DATE	INVOICE #	NAME	AMOUNT	DEEP BASIN SHOP
Jul-21		Deep Basin Shop		
15-Jul-21	139777kms	Complete inspection. Grease trailer.	Phil	1.00
Aug-21		Deep Basin Shop		
13-Aug-21	143780km	complete inpection grease trailer	Phil	1.00
		Triple 'S' Tire		
21-Aug-21	BL228018	Center axel right hade side	78.00	
Sep-21		Greatwest Kenworth		
7-Sep-21	PG3199228	Brade-spring 3030 combo	270.00	
		Triple 'S' Tire		
13-Sep-21	BL228604	Left center axle inside , customer supplied tire	40.17	
21-Sep-21	BL229015	Tire repair	60.86	
		JR's Sales and Rentals		
13-Sep-21	715820	Clip cable malleable 1/4" cable aircraft 1/4 galv	40.88	
		Fort Garry Industries		
17-Sep-21	F8927021	valve - 3way	316.20	
		Deep Basin Shop		
7-Sep-21	149200km	Washed trailer, complete inspection and grease trailer. Found L3 brake pot leaking	Phil	2.00
8-Sep-21	149200km	Replace L3 brake pot.	Phil	2.00
13-Sep-21	150450KM	Replaced LH tarp cable	Phil	1.50
16-Sep-21	151732kms	weld latch pins on box. Replaced both side marker/signal lights. Replaced tail gate control solenoid. Repaired door hinge on valve box. Installed tarp hold down on RH side. Lubed tarp cables. Replaced bearing in tarp crank.	Phil	5.50
Oct-21		Deep Basin Shop		
1-Oct-21	156960km	Grease trailer, ajust all tires to 120PSI, no inspection done	Phil	2.00
20-Oct-21	163309km	Grease trailer, replace L1 brake pot, Ajust all tire presures to 120psi	Phil	3.00
		Triple 'S' Tire		

14-Oct-21	BL229618	Drivers side middle axle inside	160.68	
26-Oct-21	BL229990	Tire repair passenger rear axel inside.	60.86	
Nov-21		Deep Basin Shop		
14-Nov-21	169119km	Complete inspection , grease trailer setup brakes	Phil	1.00
25-Nov-21	171165km	Replaced both LH side boards. Replaced LH rear side marker light.	Phil	1.50
		Beaverlodge Home Building Centre		
25-Nov-21	AV1199	Brush, treated smooth 2x10x10	101.15	
Feb-22		Fort Garry Industries		
3-Feb-22	F9184192	stainless steel chain	319.70	
		Deep Basin Shop		
3-Feb-22	174703km	Repair supply airline to R# brake pot. Repaired both rear bearings in tarp pully. Installed tarp hold down bolt on LH side board. Greased trailer, complete inspection. Realigned tarp. Installed new chain on tarp crank. Lubed tarp cable and chain	Phil	7
21-Feb-22	177454km	Wash trailer for services and brakes repairs	Phil	1.5
22-Feb-22	177454KM	removed all slack adjustments, removed R1 wheel and brakes. Installed new brakes. Installed new brake hardwRE AND WHEEL SEAL IN r1. Installed all new slack anjusters. Reinstalled R1 Wheel. Setup all brakes. Complete inspection and greased trailer. Ajusted hoist cylinder seals.	Phil	8
		Fleet Brake		
22-Feb-22	12P36631	premium asa	532.44	
23-Feb-22	12P36657	cam, cam, plate adaptor, cam tube21 long, shock absorber, gasket hubcap, seal axle	880.44	
Mar-22		Deep Basin Shop		
3-Mar-22	181888kms	Diagnose and repair wiring to control gate latches.	Phil	1
9-Mar-22	184193kms	CVIP inspection. Washed trailer for cvip inspection. Put trailer on stands and start removing wheels for brake component replacement on all wheels.	Phil	5
10-Mar-22	184193kms	CVIP repairs. Removed all wheels, all brakes, wheel hubs, s cams, and dust covers. Start installing new s cam tubes.	Phil	10

11-Mar-22	184193kms	CVIP repairs. Installed new s cam tubes, s cams, wheel seals, brake shoes on all wheels. Installed new shocks on R2 and L2. Installed wheel hubs, filled up with oil. Installed brake drums. Reinstalled slack adjusters and hooked up to brake pots.	Phil	10
14-Mar-22	184193kms	CVIP repairs. Installed all new dust covers. Installed all wheels. Rerouted brake hoses to prevent wear. Removed air control box for repairs.	Phil	6
15-Mar-22	184193kms	CVIP repairs. Welded cracks in air control box. Built and installed new mount plate for air control box. Welded cracks in front corners of gravel box.	Phil	6
		Fleet Brake		
10-Mar-22	12P38306	Camshaft, camshaft, bracket for cam tube, tube enclosure.	777.36	
11-Mar-22	12P38349	Shoe kit	419.70	
11-Mar-22	12P38410	camshaft hardware	18.78	
11-Mar-22	12P38417	seal	30.00	
14-Mar-22	12P38559	Returned seal	(30.00)	
14-Mar-22	12P38555	Returned cam, plate-adaptor, cam tube	(505.44)	
		JR's Sales and Rentals		
10-Mar-22	759890	Hydraulic fittings, fittings	26.10	
		Cassity Equipment Sales		
10-Mar-22	18861	Perform CVIP "A" full inspection, wheels off.	418.25	
Apr-22		Triple 'S" Tire		
8-Apr-22	BL234023	Right Rear alex inside, prema radial boot boot, prema truck plug PS-3 Plug	56.90	
22-Apr-22	BL234367	Tire repair.	80.34	
		Deep Basin Shop		
28-Apr-22	188849kms	Complete inspection. Grease trailer.	Phil	1
May-22		Triple 'S" Tire		
24-May-22	BL235338	Changeover tires.	80.34	
		Deep Basin Shop		
13-Jun-22	196817KM	washed trailer, complete inspection greased, repaired air leak	Phil	3
			4,233.71	

Unit #922
2019 Cross Country Pup
SN: 2C9PBK3L0KM183801

DATE	INVOICE #	NAME	AMOUNT	DEEP BASIN SHOP HOURS
1-Jul		Deep Basin Shop		
17-Jul-20	103839kms	Complete inspection and grease. Maintenance checklist complete.	Phil	1
		Justin Reaugh Welding LTD		
30-Jul-20	8761121	crack repair on box corners	110.00	
1-Aug		Deep Basin Shop		
24-Aug-20	108878kms	Complete inspection and grease. Maintenance checklist complete. Replaced hydraulic coupler on hose. Cut shield on hitch so rocks cant collect on it. Tightened license place bracket. Added more support to air box.	Phil	2
		Triple S Tire 2015		
12-Aug-20	BL216568	Tire repair-passenger center axle inside.	60.86	
1-Sep		JR's Sales and Rentals		
18-Sep-20	610100	Wika guage. 1/2" Teflon tape.	24.30	
1-Oct		Beaverlodge Home Building Centre		
7-Oct-20	AQ7017	Spruce 2x10-10'	21.99	
		Deep Basin Shop		
7-Oct-20	118181kms	Complete inspection and grease. Maintenance checklist complete.	Phil	1.00
16-Oct-20	119373kms	Replaced RH rear side board.	Phil	1.00
		Triple S Tire 2015		
7-Oct-20	BL218457	Change over tires. 2 inside rear axle and two new tires on one side and other side two old tires.	80.34	
		Deep Basin Shop		
22-Dec-20	123426	Coplete Inspection and grease	Phil	0.5
		Fort Garry Industries		
2-Feb	F8484021	seal kit for 63 cylinder, seal kit 74 cylinder	287.28	
		Deep Basin Shop		
8-Feb-21	125054km	Tightened caps on box cylinder, welded cracks on front of box.	Phil	4
1-Mar		Deep Basin Shop		
10-Mar-21	126401KM	CIVP Inspection	Phil	2

15-Mar-21	127244KM	Replace trailer light cord from hitch to junction on frame	Phil	3
16-Mar-21	127447	Cmplete inspection and grease	Phil	1
		Assault Mechaical Inc		
17-Mar-21	670	CIVP Heavy trailer Three axle	262.50	
		Deep Basin Shop		
31-May-21	131024KM	Complete inspection and grease trailer	Phil	1
1-Jun		Fort Garry industies		
3-Jun-21	F8730013	drawbar eye, bushing, rubber	431.09	
23-Jun-21	F8769417	clevis kit	95.70	
23-Jun-21	F8769378	Valve assembly. Lifeseal.	450.14	
		Deep Basin Shop		
3-Jun-21	131275km	Removed bent pintle hitch , drawbar eye, installed new hitch	Phil	2
		Complete insection and services trailer. Found ABS relay valve not functioning properly replaced R1, R2 and L2 Were leaking. Replaced R1, R2 and L2 brake pots. Replaced RH		
23-Jun-21	134464	Front marker light	Phil	8
		Triple "S" Tire		
3-Jun-21	BL225023	Rotate budd wheel	136.00	

Unit #922
2019 Cross Country Pup
SN: 2C9PBK3L0KM183801

DATE	INVOICE #	NAME	AMOUNT	DEEP BASIN SHOP
1-Aug		Deep Basin Shop		HOURS
19-Aug-19	59036kms	Service. Maintenance checklist completed.	Phil	0.5
		JR's Sales & Rentals		
20-Aug	494250	Mega flex hose.	241.08	
1-Sep		Deep Basin Shop		
3-Sep	65291kms	Greased trailer. Trimmed rubber for gate seal. Adjusted gate latches.	Phil	2
23-Sep	68965kms	Replaced air suspension. Pressure guage.	Phil	1
27-Sep	69454kms	Service. Maintenance checklist completed. Greased trailer.	Phil	0.5
		Resource Purchasing & Supply		
23-Sep	992694	Fluid stem mount.	67.90	
1-Oct		Deep Basin Shop		
16-Oct	72492kms	Service. Maintenance checklist completed.	Phil	1.5
30-Oct	74373kms	Diagnose no air to suspension or gate dump. Found valve on air tank malfunction. Ordered valve.	Phil	1
31-Oct	74373	Removed Brake priority valve and installed new one. Tested system. Ok	Phil	2
		Fleet Brake		
30-Oct	12293030084	valve spring brake control	81.12	
1-Nov		Deep Basin Shop		
2-Nov-19	74822	Service. Maintenance checklist completed. Complete inspection and grease trailer, fixed air leak on main supply to priority valve	Phil	1
14-Nov	76608	Replaced ABS valve. Replaced RH brake pot on #3 axle. Cleaned and lubed diverter valve.	Phil	5
		Fort Garry Industries ltd		
5-Nov-19	F7637844	relay valve abs	251.95	
1-Dec		Deep Basin Shop		
30-Dec-19	77853kms	Service. Maintenance checklist completed. Completed inspection & grease. Repaired wiring harness at trailer plug.	Phil	2
1-Feb		Deep Basin Shop		

13-Feb-20	81184kms	Service. Maintenance checklist completed.	Phil	1
18-Feb-20	81639kms	Replaced broken wire harness from truck plug to junction box for tailgate release.	Phil	2
1-Mar		Deep Basin Shop		
16-Mar-20	82018kms	CVIP Inspection and Repairs. Removed shocks from #3 axle	Phil	2
17-Mar-20	82018	CIVP Repairs Installed new shocks on #3 axle, Changed all hub oil	Phil	1.5
20-Mar-20	69941kms	Made brackets to mount air tank. Mounted air tank under the cross step. Ran an airline from the rear to the tank. Plump in spray want. Will need to put shut off valve for air on tank. No supply in town, told Tom about it and he was ok with it.	Derek	6
		Fort Garry Industries ltd		
17-Mar-20	F7894523	Shock-Fleetline 1-5/8"	245.40	
		Assault Mechanical Inc.		
17-Mar-20	442	CVIP Tree Axle Trailer	250.00	
20-Mar-20	550760	fittings, fittings, fittings, Valve Female pipe ends 3. 1/2 X 480 Teflon Tape, 12Mp-12 Mp, !2Mp-Plug	26.32	
1-Apr		Deep Basin Shop		
2-Apr	85666kms	Complete Inspection and grease.	Phil	1
1-May		Deep Basin Shop		
13-May	93382kms	Complete Inspection and Service. Maintenance checklist complete. Repaired trailer cord wiring. Replaced RH safety chain.	Phil	1.5
28-May	96592kms	Removed hydraulic hose from truck to lift cylinder. Had new one made at JR's. Installed on trailer. Lubed chains, pulleys and cable on tarp. Refilled hydraulic resevoir.	Phil	2
		JR's Sales & Rentals		
28-May	570620	Mega flex hose x16.5. 16G-16MPX x2.	235.41	
		Triple S Tire		
20-May	BL213593	mount tire - supplied by customer	40.17	
27-May	BL213882	Repair Driver side rear outside trailer tire.	57.86	
30-May	BL214045	Flat tire repair.	40.17	
		UFA		
28-May	*215602100756	Hyd oil x1	57.89	

28-May	*215602100759	Hyd oil x4	231.52	
28-May	*215602100758	Hyd oil x2	115.76	
1-Jun		Deep Basin Shop		
9-Jun	97846kms	Replaced hydraulic hose to lift cylinder	Phil	2
16-Jun	97847kms	Sanded front of box and repainted. Repaired tarp catches.	Phil	2
27-Jun	100103kms	Complete Inspection and Service. Complete inspection and grease. Repaired wiring on light cord.	Phil	2
		JR's Sales & Rentals		
9-Jun	576230	16G-16MPX x2. 16M2T Megaflex Hose x16.5	235.41	
		Triple S Tire		
30-Jun	BL215066	Rep MED Truck o/unit HB 20, Drivers rear inside, Prm TRUCK PLUG, Prema Prema Radial boot boot	63.91	

Unit #922
2019 Cross Country Pup
SN: 2C9PBK3L0KM183801

DEEP BASIN SHOP

DATE	INVOICE #	NAME	AMOUNT	HOURS
Sep-18				
26-Sep-18		1039282 Alberta Ltd (Plates)	109.00	
Oct-18		Deep Basin Shop		
1-Oct-18	N/A	Changed hydraulic coupler to proper stle, install 45degrees fittings on glad hands. Replace service glad hand with quick release one.	Jeff Bateman	1
2-Oct-18	N/A	Install hubodometer and secure license plate.	Jeff Bateman	1
4-Oct-18	N/A	Drill holes in bracket for suspension guage and isntall plumb guage in.	Jeff Bateman	1.5
29-Oct-18	6824kms	Serviced. Greased truck. 2.5 tubes of grease. Checked lights, checked brakes. Maintenance checklist completed.	Derek	3.5
		Justin Reaugh Welding Ltd		
3-Oct-18	#876/ 0881	Alluminum gauge bracket for weight gauge.	220.00	
		Fleet Brake		
2-Oct-18	12282750010	hubodometer, bracket	111.70	
		Resource		
3-Oct-18	916640	fuild steam mont, pipe bulkhead	71.25	
Dec-18		Deep Basin Shop		
7-Dec-18	16970kms	Serviced. Greased, set brakes, checked lights. Repaired 2 broken wires on trailer plug wiring, pinched due to over jack knifing.	Derek	5
		Trim FX Sign & Design		
12-Dec-18	23439	Decals.	5.00	
Mar-19		Fort Garry Industries Ltd		
26-Mar-19	F7203636- JEFF # 149	Artic hose 3/8" Air brake.	31.25	
		Resource Purchasing & Supply		
26-Mar-19	955504- JEFF #149	Male pipe swivel X2. 1" 2wire hydraulic hose X201. M pipe/fm pipe 45 deg.	223.60	
26-Mar-19	955593- JEFF #149	160 PSI 4" fluid stem mount.	80.90	
Apr-19		Assault Mechanical Inc.		

3-Apr-19	#149	CVIP inspection. Tailgate latch not clearing pins on tailgate properly. Open tailgate & prop open for access. Trim latches & test operation. OK. Suspension gauge damaged. 7 pin male electrical plug damaged, hydraulic line damaged, airlines for supply & service airlines damaged. Replace 6 pin plug & cord. 7 pin plug, hydraulic line, airlines & glad hands.	1,939.66	
		Deep Basin Shop		
29-Apr	37224kms	Maintenance checklist completed. 1/2 tube of grease. Fixed air leak. (drain valve 2nd tank). Greased unit.	Phil	0.5
Jun-19		Deep Basin Shop		
6-Jun-19	44856kms	Greased trailer.	Phil	0.5
25-Jun-19	50823kms	Service & inspection. Maintenance checklist completed.		